

FL 102

Fume cupboard exhaust air flow alarm

The FL 102 alarm system warns the employee, for example, of the following fume cupboard malfunctions:


The fan does not work

The sash is too open

Strong external flow disturbance

Fanison Oy

Vesijärvenkatu 25 C 2, 15140 LAHTI
fanison@fanison.fi
+358 40 843 0032
fanison.fi



System properties

- The alarm is transmitted to the employee by flashing lights and sound signals
- The alarm is programmed with the push buttons for the desired features
- Alarm transmission is possible (2 relays)
- It is easy to install the alarm in the fume cupboard afterwards
- The delivery includes a transformer (to be installed in a socket)

Fanison Oy

Vesijärvenkatu 25 C 2, 15140 LAHTI
fanison@fanison.fi
+358 40 843 0032
fanison.fi