



FL 102

Fume cupboard exhaust air flow alarm


The FL 102 alarm system warns the employee, for example, of the following fume cupboard malfunctions:


The fan does not work


The sash is too open


Strong external flow disturbance

Fanison Oy


 Vesijärvenkatu 25 C 2, 15140 LAHTI

 fanison@fanison.fi

 +358 40 843 0032

 fanison.fi





System properties

- The alarm is transmitted to the employee by flashing lights and sound signals
- The alarm is programmed with the push buttons for the desired features
- Alarm transmission is possible (2 relays)
- It is easy to install the alarm in the fume cupboard afterwards
- The delivery includes a transformer (to be installed in a socket)

Fanison Oy

- 📍 Vesijärvenkatu 25 C 2, 15140 LAHTI
- ✉ fanison@fanison.fi
- ☎ +358 40 843 0032
- 🌐 fanison.fi

